

<b>JSC Safety and Health Handbook</b>	JPR No.	<b>1700.1K</b>
	Effective Date:	<b>11/25/2013</b>
	Expiration Date:	<b>11/25/2018</b>
	Page Number	Page 8.4-1 of 4

## Chapter 8.4 Welding, Cutting, and Brazing Safely

### ***This could be you . . .***

***A welder was welding on a pressure vessel suspended from a chain hoist when the hook on the hoist turned cherry-red hot. The welder had forgotten to ground his work piece. The arc welding system had found its own ground path through the vessel, through the hook on the hoist, through the building structure, and back to the welding machine. No one was injured, but the work was delayed for extra inspections because of the improper ground connection.***

***Two welders were welding on an overhead bridge crane when sparks fell approximately 40 feet into a titanium and magnesium scrap metal container below, causing a fire in the container. No one was hurt, but time was lost in the machine shop due to the evacuation of the building and the cleanup resulting from the fire.***

### **8.4.1 Applicability of this chapter**

You are required to follow this chapter if you do arc or heliarc welding, gas welding, gas cutting, or brazing.

### **8.4.2 General requirements for welding, cutting, or brazing**

8.4.2.1 You shall follow the general requirements given below:

- a. Follow the requirements in 29 CFR 1910, Subpart Q (1910.252 – 255).
- b. Have a copy of the MSDS/SDS in your shop for every type of welding rod used.
- c. Have a valid JSC Form 1475, "Hot Work-Welding-Cutting Permit," for all burning, cutting, or welding operations in all areas other than welding shops. See Chapter 5.8, "Hazardous Operations: Safe Practices and Certification," paragraph 5.8.12, of this Handbook for more information. To create a permanent welding or hot work area, follow the procedure in Chapter 5.8, paragraphs 5.8.9–5.8.11.
- d. Complete and get approvals on a JSC Form 992, "Confined Space Entry Procedure," and JSC Form 1476, "Confined Space Entry Permit," for all welding operations done in confined spaces. Welding in a confined space will change the space classification to an OSHA-permitted confined space. See Chapter 6.10, "Entering Confined Spaces," of this Handbook.
- e. Observe the requirements of Chapter 5.6, "Personal Protective Equipment," for fall protection and Chapter 8.7, "Ladders, Scaffolds, and Elevated Platforms: How to Work with Them Safely," of this Handbook when working at heights of 4 feet or more above adjoining surfaces.
- f. Keep welding cable and other equipment clear of all areas where others may be working.
- g. Have protective equipment, such as helmets, shields, aprons, gloves, gauntlets, and other personal protective clothing required for each individual on the job, as described in 29 CFR 1910.252.(b)(2) and (3).

Verify correct version before use at

<http://server-mpo.arc.nasa.gov/Services/CDMSDocs/Centers/JSC/Home.tml>.

JSC Form JF2420B (MS Word.....)

<b>JSC Safety and Health Handbook</b>	JPR No.	<b>1700.1K</b>
	Effective Date:	<b>11/25/2013</b>
	Expiration Date:	<b>11/25/2018</b>
	Page Number	Page 8.4-2 of 4

- h. Observe the requirements of Chapter 7.2, “Respiratory Protection,” when welding activities could cause exposures to exceed established limits for metal fumes. Contact the Occupational Health Branch for evaluation.
- i. Never weld, cut, or braze painted surfaces. The paint may contain lead, chromium, or other hazardous compounds that will cause significant toxic exposures when heated or burned. You shall properly remove the paint before welding, cutting, or brazing. OSHA has regulations governing the proper removal of paint containing lead, chromium, and other metals. If you are not sure about the compounds in the painted surfaces, contact the Occupational Health Branch, x36726. They will analyze the paint and provide recommendations for the safe removal of the paint.

### **8.4.3 Fire precautions for welding, cutting, and brazing operations**

8.4.3.1 You shall take the following fire precautions:

- a. Observe the requirements of Chapter 5.1, “Fire Safety,” of this Handbook.
- b. Provide and maintain suitable fire extinguishing equipment for instant use.
- c. Provide a properly trained fire watch for all welding or cutting operations where other than a minor fire may develop. A fire watch shall stay at the work site for at least 30 minutes after the hot-work operation. See Chapter 5.8, “Hazardous Operations: Safe Practices and Certification,” paragraph 5.8.9, of this Handbook for more information.
- d. Before starting the job, remove, guard, or cover all materials or structures that might catch fire with a fire-resistive covering. This includes the bottled gas.
- e. Where practicable, move all combustible materials at least 35 feet from the work site.
- f. Take precautions to prevent sparks or slag from falling onto combustible material below through floor openings or cracks that can’t be covered.
- g. Don’t weld, cut, or braze any unidentifiable material.
- h. Have all areas and vessels that could have flammable or explosives materials present checked out by the Occupational Health Branch.
- i. Don’t weld, cut, or braze near flammable or explosives materials.

### **8.4.4 When to use mechanical ventilation for welding**

8.4.4.1 You shall have adequate local ventilation, such as an exhaust hood or snorkel that meets the requirements of 29 CFR 1910.252(c) under the following conditions:

- a. When required by 19 CFR 1910.252(c)(2)(i).
- b. When welding, cutting or brazing any metals listed in 29 CFR 1910.252(c)(5) – (12).
- c. When welding in a room in which it is recommended by the Occupational Health Branch to control exposures to welding fumes.

<b>JSC Safety and Health Handbook</b>	JPR No.	<b>1700.1K</b>
	Effective Date:	<b>11/25/2013</b>
	Expiration Date:	<b>11/25/2018</b>
	Page Number	Page 8.4-3 of 4

#### **8.4.5 General requirements for welding, cutting, or brazing in a confined space**

8.4.5.1 You shall:

- Observe the requirements of Chapter 6.10, "Entering Confined Spaces and Controlled Areas," of this Handbook.
- Observe the requirements in 29 CFR 1910.252(b)(4).

#### **8.4.6 General requirements for gas welding**

8.4.6.1 You shall:

- Follow the requirements in 29 CFR 1910.253.
- Use the special T-wrench to open the cylinder and leave it close to the cylinder for emergency use.
- Have flashback protection on the cylinder.
- Only use oxygen cylinders, gauges, regulators, valves, and fittings that are rated and identified for oxygen use.
- Store cylinders per 29 CFR 1910.253(b)(2) – (4).

#### **8.4.7 Caring for hoses**

8.4.7.1 You shall properly care for your hoses by:

- Protecting the hoses from damage.
- Visually inspecting the hoses for leaks.
- Repairing or replacing hoses that are damaged.
- Using only standard ferrules or clamps on all hoses.
- Not using tape or wire for holding hoses onto attachment points.
- Regularly operating any relief valves to make sure that they work.
- Never using bootleg adaptors that allow hoses to be used for non-specified connections.

#### **8.4.8 Requirements for arc welding**

8.4.8.1 You shall:

- Follow the requirements in 29 CFR 1910.254.
- Connect the ground return line securely.
- Do not ground the welding generator. This supplies a second current path through building steel.
- Protect auxiliary 240/120 volt outlets from the generator with a GFCI at the generator.
- Ground the work piece properly.
- Check connections before starting the welding machine.

<b>JSC Safety and Health Handbook</b>	JPR No.	<b>1700.1K</b>
	Effective Date:	<b>11/25/2013</b>
	Expiration Date:	<b>11/25/2018</b>
	Page Number	Page 8.4-4 of 4

- g. Wear appropriate PPE as called out on the MSDS/SDS, by your supervisors and by the governing safety and health plan.
- h. Make sure that your helper also wears appropriate PPE when working on or near welding, cutting, brazing, or grinding operations.
- i. Use helmets, shields, and appropriate clothing to protect against flash burns, sparks, or flying particles.
- j. Protect terminals for welding leads against accidental electrical contact by personnel or metal objects.

#### **8.4.9 Certification required for welding at JSC**

8.4.9.1 For the safety of all personnel, you shall be certified for the welding process, material, and hardware type you will be welding. Use the certification requirements in the following publications that are appropriate to what you are welding:

- a. Flight Hardware – AMS-STD-1595, “Qualification of Aircraft, Missile, and Aerospace Fusion Welders”
- b. Structural Hardware – AWS B2.1, “Specification for Weld Procedure and Performance Qualification”
- c. Pressure Systems – American Society of Mechanical Engineers (ASME) Section IX, “Welding and Brazing Qualifications”

#### **8.4.10 For more information on welding, cutting, and brazing**

- a. 29 CFR 1910, Subpart Q, “Welding, Cutting, and Brazing”
- b. NIOSH 75-115, “Engineering Controls for Welding Fumes”
- c. NIOSH 77-131, “Welding Safety”
- d. NIOSH 78-138, “Safety and Health in Arc Welding and Gas Welding and Cutting”
- e. NIOSH 79-125, “Assessment of Selected Control Technology Techniques for Welding, Fumes”